

Mine Name: Brown Rock 7

Operator Name: Wellmans Minerals Corp.

## State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

## Inspection Report Minerals Regulatory Program

Date: March 12, 2009

Reviewed:	PRY	
		•

Permit Number: S/045/0055

Inspection Date: 06-11-2008

Inspector(s): L Heppler	Time:11:00 AM Mine Status: PRO		
Other Participants: none			
<b>Elements of Inspection</b>	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	$\boxtimes$	$\boxtimes$	
2. Public Safety (shafts, adits, trash, signs, highwalls)	$\overline{\boxtimes}$		
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,			
8. Soils	$\boxtimes$		
9. Revegetation	$\overline{\boxtimes}$		

Bond Amount: \$3785 Bond Renewal Date: 09-13-2005 Permit fee is up to date

Purpose of Inspection: Routine annual Inspection

**Inspection Summary:** Several exploration roads have recently been pushed by a dozer. None reclaimed with a trackhoe. No topsoil or growth medium has been stockpiled.

Photos were taken to document site conditions.

Conclusions and Recommendations: Bond is not consistent with surface disturbance. Bond held by BLM. DOGM Permit should be closed out. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

cc: Walter Wellman

Larry Garahana@blm.gov Stephen Allen@blm.gov

O:\M045-Tooele\S0450055-BrownRock-RockingChair\inspections\insp-06112008.doc

